

NY Thermal Inc.
Tel: (506) 657-6000
Toll Free: 1-800-688-2575
Fax: 1-506-432-1135
Web: www.nythermal.com
Email: info@nythermal.com

83213-1

Flue Outlet Adapter Kit (Lx300-400)

Comes with flue pipe gasket, test port plug, and warning decal

Applicable Boiler Models

- Lx300
- Lx400

Kit Contents

- 83213 Flue Outlet Adapter c/w Gasket (GM10-15-992-01)
- 84054 Test Port Plug, Viton
- 84086 Flue Gas Test Port Warning Decal

Tools Required

- Saw for cutting the venting
- Applicable vent glue and primer
- 5/16" nut driver
- Refer to boiler installation manual for approved
- vent materials



Figure 1 - Flue Outlet Adapter Kit



Sharp Edges – The flue adapter may have sharp edges. Use gloves

or other protective equipment to prevent injury. Failure to follow instructions could result in minor or moderate personal injury.

Replacement Instructions

- 1) Turn off power to the appliance.
- 2) Remove the vent pipe
- 3) Remove the flue adapter by “rocking” it side to side while pulling up on it. (wear gloves to avoid injury)
- 4) Inspect the flue adapter receptacle rubber seal for improper alignment or damage



Heat Exchanger Seal – The boiler heat exchanger has an integral rubber seal to prevent flue gas leakage; failure to properly inspect this gasket may result in flue gas leakage causing serious injury or death.

- 5) Install the new flue adapter by placing it squarely over the opening and applying even pressure to the top of the adapter, until it “snaps” into place.
- 6) Inspect the flue adapter seal and ensure that it is properly aligned and seated



Flue Pipe Seal – The flue adapter is provided with an integral rubber seal to prevent flue gas leakage; failure to ensure this gasket is in place will result in flue gas leakage causing serious injury or death.

- 7) Ensure that the flue pipe inserted into the flue adapter is beveled to remove sharp edges and reinstall into the flue adapter
- 8) Ensure the test port plug is pushed in place and secure.
- 9) Operate the boiler and test for leaks.



Test Port Plug – The flue adapter is provided with a combustion test port and plug. Failure to properly secure the test port plug may result in flue gas leakage which may lead to serious injury or death.