



NY Thermal Inc.
Tel: (506) 657-6000
Toll Free: 1-800-688-2575
Fax: 1-506-432-1135
Web: www.nythermal.com
Email: info@nythermal.com

83915

High vent pressure switch AFS460-367(Lx300-400)

1.8" NC gold contacts

Applicable Boiler Models

- Lx300
- Lx400

Kit Contents

- 1 High vent pressure switch

Tools required:

- 1/4" nut driver
- 1/2" open ended wrench

Replacement Instructions

- 1) Turn off power to the appliance
- 2) Remove the metallic tubing by loosening the brass nut. Note: the Brass nut will remain attached to the metallic tubing.
- 3) Remove switch and reinstall the new switch in the reverse order
- 4) Test metallic tubing connection for leaks with combustion blower running



WARNING **Metalic Air Switch Tubing** – The metalic air switch tubing contains air and fuel while the burner is operating. Failure to properly secure this tubing and test for leaks may result in fire, explosion, serious injury or death.

WARNING **Combustion chamber cleaning-** This air switch is intended to trip when the boiler has an excessively dirty combustion chamber or restricted exhaust venting. Failure to properly clean the appliance or remove exhaust restrictions will cause improper burner operation which may result in serious injury or death.