



NY Thermal Inc.  
Tel: (506) 657-6000  
Toll Free: 1-800-688-2575  
Fax: 1-506-432-1135  
Web: www.nythermal.com  
Email: info@nythermal.com

**85054-1** (Replaces 83707)

# Spark Generator Carlin

C/W Spark igniter wire and Silicone boot

### Applicable Boiler Models

- Lx150-800
- Tft60-399
- Tx51-200
- Tx151(C)
- Tx200(C)

### Tools Required

- Phillips #2 Screw Driver
- 1/4" Nut Driver

### Kit Contents

- 85054 Spark Generator Carlin Replaces 83707
- 85055 Ignition Cable
- 85140 Silicone Tube 7/8" Id



This boiler must be serviced by a qualified heating technician. Failure to properly maintain or service this appliance may result in property damage, serious injury to occupants or, death.



The installation of this kit must be performed by a qualified boiler technician. Installing this kit without the proper background and training is hazardous and may result in property damage or death.

**\*\* Use all parts included in this kit when replacing the Honeywell transformer \*\***

